

Mercedes-Benz Actros 1945 | Hydraulic | Retarder | 521089Km | 2019 | Smart Tacho 2 | Stand Klima | Euro6 | TUV/MOT/APK 02-2027 | Belgium Truck

Yleiset ominaisuudet

Merkki	Mercedes-Benz
Malli	Actros 1945
Alaluokka	Ohjaamonosturi
Mittarilukema	521.089km
Rakennusvuosi	2019
Ensimmäisen rekisteröinnin päivämäärä	08-02-2019
Väri	Nokkeluus
Kunto	Käytetty
Yleinen tila	Erittäin hyvä
Polttoaine	diesel-
Päästöluokka	Euro 6



Ominaisuudet

Yksittäinen paino	8.097kg
Kantavuus	10.903kg
Kokonaispaino	19.000kg
Pituus	616cm
Leveys	250cm
Mökki	Makuuhuone
Sarjanumero	NMB96340312190706
Sylinteritilavuus	12.809cc

Tekniset tiedot

Akseleiden lukumäärä	2
Akselin konfiguraatio	4x2
Tarttuminen	Automaattinen
varat	330kw

Kuvaus

Mercedes-Benz ACTROS 1945 Hydraulic Retarder 521089Km 2019 Smart Tacho 2 Stand Klima A/C Fridge 2 Unused sleeping beds Cruise Control Toolbox Automatic gearbox Euro6 4X2 TUV/MOT/APK 02-2027 Belgium Truck VIN: NMB96340312190706 Video of the truck (Youtube): <https://youtu.be/KiOmRe5H-w> EXPORT SERVICES ————— • Austrian transit registration/number plates with insurance for 21 days • Transport to each port in the Netherlands and Belgium • Truck transport with trailer Prices for export services are exclusive the asking price of the advertisement, feel free to contact us for the possibilities **No rights can be derived from incorrect information in the advertisement. GEERTS Trucks & Trailers does its best to ensure that all information is correct**

Asusteet

- Anti-lock braking system
- Air conditioning
- Aluminium fuel tank
- Leaf spring suspension
- Central locking
- Cruise control
- Roof spoiler
- Electrically operated windows
- Toolbox
- Refrigerator
- Air horn
- Air suspension
- Fog lights
- PTO
- Particulate filter
- Sleeper cab
- Speed limiter
- Stability control
- Vehicle heater
- Spotlights
- Side door
- Visor
- Trailer coupling
- Power steering
- Passenger seat
- Airbags
- Radio/Cd/Audio system
- EBS
- Climate control
- Retarder
- Heater
- Alarm
- ASR (Anti-Slip Regulation/Traction Control)
-
-
-
-
-